

# CONSEQUENCES OF NOT MAINTAINING ADEQUATE RAIL NEUTRAL TEMPERATURE

FRA Track Safety Symposium  
St. Louis, MO  
April 5, 2022


*Brad Kerchof*  
*Advanced Rail Management*  
*Norfolk Southern Railway (retired)*

## KEY CONCEPTS

T109	FRA cause code for track alignment irregular (buckled/sunkink)
RNT	Rail Neutral Temperature
$\Delta T$	Change in temperature; also difference between RNT and actual rail temperature
$\Delta T$ of 60°F	Threshold for wood tie track buckling
Typical rail temp range	-20° to 135°F (ambient -20° to 100°F)
Solar Absorption	The increase in rail temperature above ambient caused by solar radiation



## T109 TRACK ALIGNMENT IRREGULAR (BUCKLED/SUNKINK)




## WHAT IS RAIL NEUTRAL TEMPERATURE (RNT)?

- Temperature at which rail is neither in compression nor tension
- Temperature at which rail is (longitudinally) stress-free
- Temperature at which rail is installed



## WHY IS RNT IMPORTANT?

Knowing RNT allows us to manage the risk of buckled track



NS file photo



# RELATIONSHIP BETWEEN RAIL LENGTH AND TEMPERATURE


$$\delta_T = a \cdot \Delta T \cdot L$$

Where

- $\delta_T$  – change in length due to change in temperature (inches)
- $a$  - coefficient of thermal expansion for steel ( $6.6 \times 10^{-6}$  in/in/°F)
- $\Delta T$  - change in temperature (°F)
- $L$  - initial length (inches)

For a 100-ft piece of rail,  $\Delta T$  of 60°F results in  $\delta_T = 0.5$  inches

For 1440 ft of welded rail,  $\Delta T$  of 60°F results in  $\delta_T = 6.6$  inches



## WHAT IS A REASONABLE RNT?

One railroad's standard procedure:


- ✓ Install at 95°F (40° below likely max rail temp)
- ✓ Use a rail heater if temperature is less than 80°



## WHAT CAUSES TRACK TO BUCKLE?

A large  $\Delta T$  (a large difference between RNT and actual rail temp); on wood tie track, at least  $60^{\circ}$ .

Typically...the root cause of a track buckle is not that the actual rail temp has gotten too high.... It's that RNT has gotten too low.






## WHAT CAN CAUSE LOW RNT?



Repairing this broken weld will add close to 3 inches of rail (rail temp at the time was 20°F)



This curve pulled inward in cold weather (note voids at the ends of the ties)

## WHAT CAN CAUSE LOW RNT?

- 1) Laying rail at too low a temperature
- 2) Adding rail by cutting in a longer piece than is cut out
- 3) Adding rail by making thermit welds when joints are pulled open
- 4) A curve pulls inward during cold weather, shortening its length
- 5) Insufficient rail restraint – rail moves longitudinally under train traffic (due to insufficient or ineffective anchors), causing an increase in RNT at one spot and a decrease in RNT at another spot
- 6) Heat transfer from wheels, caused by a train traveling down grade with air brakes applied (this does not change RNT; rather, it can cause an unusually high actual temp)



## CONSEQUENCES OF LOW RNT

**Next up: Four buckled track derailments caused by low RNT due to.....**

- Adding rail by cutting in a longer piece than was cut out (during cold weather)
- Adding rail by making thermit welds when joints are pulled apart (during cold weather)





# CONSEQUENCE OF LOW RNT (#1)

## Mt. Airy, GA - August 2012

- Preceding November – Installed 4 stock rails, 4 switch points & both rails between switches, rail temp 60°.
- January – A dozen thermite welds at temps between 14° and 53°; 2 inches added to each side, according to welders' rail-added reports.
- August 1 - Buckled track derailment, air temp 91°

## Rail temp analysis

- RNT est. 20° - 50°, actual rail temp 110°,  $\Delta T > 60^\circ$



NS file photo

## CONSEQUENCE OF LOW RNT (#2)

### Bowler, VA - May 2012

- February – Removed a no. 20 turnout, installed a no. 10 turnout and 3 track panels. Temperature was in the upper 40's. No rail-added report.
- March – 18 thermite welds at temps between 50° and 60°. No rail-added report.
- May 16 – Buckled track derailment, air temp 83°

### Rail temp analysis

- RNT est. 50°, actual rail temp 110°,  $\Delta T$  60°







## CONSEQUENCE OF LOW RNT (#3)

McVey, PA - April 2017

- January - Installed two 95-ft rails between two no. 20 turnouts, temp 28° N rail and 44° S rail; rail added 1/4" and 1/8".
- February – 6 thermite welds at 41°; 0" rail added.
- April 14 forecast – high temperature of 69°

Feeling any anxiety?



NS file photos


## CONSEQUENCE OF LOW RNT (#3)

### McVey, PA - April 2017

- January - Installed two 95-ft rails between two no. 20 turnouts, temps 28° N rail and 44° S rail
- February - Thermite welds at 41°
- April 14 – **Buckled track derailment, air temp 69°**

### Rail temp analysis

- RNT 28° - 44°, actual rail temp est. 95° by ENSCO rail prediction model,  $\Delta T$  60°



## CONSEQUENCE OF LOW RNT (#4)

### Rural Retreat, VA - April 2019

- Preceding November - Installed 42 ft. rails on H and L sides through crossing; joints thermite welded; temp < 30° for all of this work.
- January – Changed out Sperry rail adjacent to crossing on H rail; joints thermite welded; temp < 30°.
- Crossing was on the supervisor's rail-added list; adjustment waiting for warm weather.
- April 6 forecast: temperature in the mid 60's

Feeling any anxiety?




NS file photo

## RAIL ADDED DATA WAS RECORDED PROPERLY (#4)

RIGHT RAIL					
Date	Rail Added	MP		Work	Temp
11/14/2018	1	NB	348.95	Rail change-out thru xing	27
11/27/2018	0.5	NB	348.95	Thermite Weld	29
11/28/2018	0.5	NB	348.96	Thermite Weld	25
1/31/2019	0.5	NB	348.97	Sperry Defect	18
<b>TOTAL</b>	<b>2.5</b>				

LEFT RAIL					
Date	Rail Added	MP		Work	Temp
11/14/2018	1	NB	348.95	Rail change-out thru xing	27
11/28/2018	0.75	NB	348.95	Thermite Weld	24
<b>TOTAL</b>	<b>1.75</b>				

## ENSCO RAIL TEMPERATURE PREDICTION MODEL (#4)



- The accuracy of the model was validated when we measured actual rail temp of 88° at 6:00 pm
- Note difference between ambient (64°) and predicted rail temp (101°) at 3:00 pm (time of derailment)
- The impact of solar radiation was substantial – predicted rail temp was 37° above ambient

### Rail temp analysis

- RNT < 30°, actual rail temp est. 101° by ENSCO model,  $\Delta T > 60^\circ$



# OBSERVATIONS FROM THESE FOUR DERAILMENTS

## 1<sup>st</sup> & 2<sup>nd</sup> derailments

- 150+ ft of rail changed out and welds made at temperatures between 40° & 50°
- Rail added recorded at only one of site
- Neither site was “on the list” for adjustment. Air temps at time of derailment were 83° and 91°

## 3<sup>rd</sup> & 4<sup>th</sup> derailments

- 40 - 95 ft of rail changed out and welds made at temperatures between 18° and 44°
- Track folks did an excellent job documenting rail added
- Both sites were “on the list” for adjustment
- Track buckled at a surprisingly low air temperature – in the 60’s!



## WHAT TO TAKE AWAY FROM THIS PRESENTATION

- 1) Most buckled track derailments are related to something that happened during cold weather (track shift, rail change-out or welding) that resulted in a lower RNT.
- 2) How you handle these cold-weather changes to RNT is key to managing your risk of buckled track.
- 3) Keep a record of any trackwork (or curve shifts) that results in a lower RNT. Then adjust that rail at your first opportunity come warm weather.
- 4) Track buckling is determined by  $\Delta T$ , not ambient temperature.
- 5) FRA data shows that the majority of buckled track derailments occur near fixed assets – a turnout, road crossing or bridge. My suspicion: Rail change-outs (and welding) are likely to occur at these locations.

## QUESTIONS?



This misalignment is not a heat buckle – its shape is not the typical “S” found in tangent track (like the heat kink above).

Rather, this misalignment was caused by a severe train run-in, which pushed two-car lengths of track to one side.